Tanks Data		30 DAYS	WALK THROUG	HINSPE	CTION
UST Facility I.D.((FID)# 787	Contact	Contact Number			
Facility Name (000000)	Contact	Contact email			
Address 109 Lincolnuay F. 46350	Date of 1	Date of Inspection 10-16 - 20 35			
Operator on Duty Name		the Person	1. 12b200	1	
O	perator Tra	ing Inspection	0		
Operator Training current	Yes	No	OperatorNotified	Yes	(No
Registra	tion/Notific	ation Form			
Is Registration current with correct owner, operator etc.	Yes	Ovo	OperatorNotified	Ores	Olo
	elease Detec	tion			
Release Detection Method	MTG	CIM	SIR	OIC	Other
Make and Model // \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \ \	150				
Does it have paper?	Yes	ON _o	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	ONo	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	ON ₀	OperatorNotified	Tes	Ovo
	pill Buckets	S A			
re Spill Buckets Clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	es	Olo
re the Spill Bucket in good condition and free of damage/cracks	Fill Ports	ONO	OperatorNotified	Oes	Olo
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Olo
Are Sumps Clean and free from water, debris, product etc?	1g/STP Sun	1ps			
위에서 발생한 이 이번에 가장 없었다. 이 전에서 되었다면 생각이 되었다면 생각이 되었다면 되었다면 되었다면 이 이 사람들이 되었다면 되었다면 되었다면 되었다면 되었다면 되었다. [15] [25] [25] [25] [25] [25] [25] [25] [2	res	CNO	OperatorNotified	Ves	Olo
Are LIDCs alone and Gree Green water debrie meducated		· .			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified (Yes	ONO
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSE FOLLOWING PROPER PROCE	SED OFF A DUE BY A	CCORDING T CERTIFIED C	ONTRACTOR.	AND REQU	LATIONS
ator on Duty Name		Signature		Date	
317-645-0215 tanksdata	@gmail.com	n		www.tanksd	
					2022051