

AUTOMATIC TANK GAUGE (ATG) FUNCTIONALITY

DATA SHEET

DATE AND TIME	3/13/2023
WEATHER	35 Snowy
COLLECT/INVOICE	Collected
CLIENT E-MAII	

Testin			

Test Location Information		Certifications	Name	Midwest Tank Testing	
PC # and WO #		Estabrooks: 82-1906	Address	316 W. Indiana Ave.	
Name and FID #	Citgo - FID 16409	ICC: 10221928	City/State/Zip	Chesterton, IN 46304	
Address	509 US Hwy 20	Indiana: UC 110386	Phone	800-975-1436	
City/State/Zip	Michigan City, IN 46360	CP/STI: 16655	Technician Information		
Contact			Name	Chris Zell	
Phone			Email	support@midwesttanktesting.com	

AUTOMATIC TANK GAUGE (ATG) FUNCTIONALITY TEST

This procedure is to determine whether the automatic tank gauge (ATG) is operating properly. See PEI/RP1200 Section 8.2 for the inspection procedure. This procedure is applicable to tank level monitor stems that touch the bottom of the tank when in place.

•							
	TLS	350					
1	2	3	4				
Premium	Regular N.	Regular S.	Diesel				
96	96	96	96				
81	81	81	81				
Yes	Yes	Yes	Yes				
Yes	Yes	Yes	Yes				
Yes	Yes	Yes	-				
Yes	Yes	Yes	-				
81	81	81	-				
Yes	Yes	Yes	-				
3	3	3	-				
Yes	Yes	Yes	-				
' the systen	n has failed	the test.					
Pass	Pass	Pass	Fail				
	Premium 96 81 Yes Yes Yes 3 Yes ' the system	1 2 Premium Regular N. 96 96 81 81 Yes Yes Yes Yes Yes Yes 81 81 Yes Yes 3 3 Yes Yes ' the system has failed	Premium Regular N. Regular S. 96 96 96 81 81 81 Yes Yes Yes Yes Yes Yes Yes Yes Yes 81 81 81 Yes Yes Yes 3 3 3 Yes Yes Yes the system has failed the test. Yes	1 2 3 4 Premium Regular N. Regular S. Diesel 96 96 96 96 81 81 81 81 Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes - 81 81 81 - Yes Yes Yes - Yes Yes Yes - Yes Yes Yes - 'the system has failed the test. - -	1 2 3 4 Premium Regular N. Regular S. Diesel 96 96 96 96 81 81 81 81 Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes - 81 81 81 - Yes Yes Yes - 3 3 3 - Yes Yes Yes - 'the system has failed the test.	1 2 3 4 Premium Regular N. Regular S. Diesel 96 96 96 96 81 81 81 81 Yes Yes Yes Yes Yes Yes Yes - Yes Yes Yes - 81 81 81 - Yes Yes - - 3 3 3 - Yes Yes Yes - The system has failed the test. - -	1 2 3 4 Premium Regular N. Regular S. Diesel 96 96 96 96 81 81 81 81 Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes Yes 81 81 81 - Yes Yes Yes - 3 3 3 - Yes Yes Yes - 'the system has failed the test. - -

Comments: Premium and regular ATG wires need repaired. I tried to test dsl but when I took it out it no longer recognized there was a probe, but I did not see any evidence of damage to the wire. I used my pliers to lock it down and it still did not work.



INDIANA HOMELAND SECURITY



Underground Storage Tank

CHRIS ZELL 316 W INDIANA AVE CHESTERTON, INDIANA

STATE/PERMIT #	ISSUE	EFFECTIVE	EXPIRATION
UC111987	12/29/2022	12/30/2022	12/29/2024
	DISCIPLINES		
✓ Installation or Retrofitting	Sec. of a	Decommission	ing Closure
Cathodic Protection		Decommission	ing Removal
Testing			

The attached testing was completed at this site by an IDHS certified technician.

Technician's Signature:

Chris Zell



316 W. Indiana Ave. Chesterton, IN 46304 (800) 975-1436 Serving the Midwest Since 1990