	30 DAYS WALK THROUGH INSPECTION			
	30 DAIS VI			
Tanks Data	Contact Number			
UST Facility I.D.((FID)# 16 400	The state of the s	Contact email		
Facility Name (()	Date of Inspection	14-10	2	
Address 569 1 EUS Huy 20167	Name of the Person	1- 0	1	
Operator on Duty Name	Conducting Inspection	Gurpre	4	
	Operator Training No	OperatorNotified	OYes	Ovo
H. [1] 전에 대한 사람들은 전경 그림은 다른 그림은 모든 말이 되는 것이 되는 것이 되었다. 그리고 있는 그림은 다른 그리고 있는 것이 있는 것이 없는 것이 생각하게 하면 하는데 얼마를 하지 않는데 다른 것이 되었다.	Registration/Notification Form	OperatorNotified	Ores	Oio
Is Registration current with correct owner, operator	Release Detection CIM	OSIR	Orc	Other
Release Detection Method Make and Model VRTZ Does it have paper? Is it in Alarm mode? Interstitial Monitoring Sensor Status Normal	5- 35 (No	OperatorNotified OperatorNotified OperatorNotified	Yes	Qio Qio Qio
Necessary Monthly Printout Taken	Spill Buckets	OperatorNotified OperatorNotified		Oxo
Are Spill Buckets Clean and free from water, debris, produ Are the Spill Bucket in good condition and free of damage	e/cracks Xes ONo	OperatorNotified	Bes	010
Is Fill pipe cap tight and fill pipe free from any obstruct	L'HILL OLLO	OperatorNotified	Oes	Oio
Are Sumps Clean and free from water, debris, product eto		OperatorNotified	Ores	Oio
		OperatorNotified	Yes	()io
Are UDCs clean and free from water, debris, product e				ULATIONS
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST B FOLLOWING PROPI	ER PROCEDUE BI A CERTIFIED C	ONTRACTOR.	1	
erator on Duty Name	Signature		Date	
317-645-0215	tanksdata@gmail.com		www.tanks	sdata.com 2022051