

PRIYA LUCKY EXPRESS

5307 Western Ave

South Bend, In

574-288-9110

INSTAL, BY B&B EQUIPMENT

12/22/2024

5:22 PM

REGULATORY REPORT

HARDWARE STATUS

TS-CIM	NOT INSTALLED
TS-ROM	NOT INSTALLED
TS-SEM 1	NOT INSTALLED
TS-SEM 2	NOT INSTALLED
TS-CPM	NOT INSTALLED
PRINTER	OPERATIONAL
FAX/MOD	OPERATIONAL

PROBES

PROBE 1	OPERATIONAL
PROBE 2	OPERATIONAL
PROBE 3	OPERATIONAL
PROBE 4	OPERATIONAL

AUXILIARY INPUTS

AUX IN 1	OPERATIONAL
AUX IN 2	OPERATIONAL

PASSED LEAK TESTS

TANK 1

07/04/2016	3:14 AM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH

TANK 2

02/06/2023	6:59 AM
LEAK TEST	0,20 GPH
SLOPE	0,00 GPH

TANK 3

12/16/2024	2:34 AM
LEAK TEST	0,20 GPH
SLOPE	-0,00 GPH

11/25/2024	3:24 AM
LEAK TEST	0,20 GPH
SLOPE	-0,06 GPH

11/11/2024	3:04 AM
LEAK TEST	0,20 GPH
SLOPE	-0,09 GPH

09/16/2024	3:19 AM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH

08/26/2024	3:19 AM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH

02/05/2024	3:39 AM
LEAK TEST	0,20 GPH
SLOPE	-0,01 GPH

12/18/2023	3:19 AM
LEAK TEST	0,20 GPH
SLOPE	-0,03 GPH

TANK 4

12/16/2024	1:14 AM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH

11/25/2024	1:14 AM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH

10/28/2024	12:59 AM
LEAK TEST	0,20 GPH
SLOPE	0,00 GPH

10/07/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH
09/09/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.00 GPH
08/12/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH
07/08/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.02 GPH
06/10/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.00 GPH
05/13/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.02 GPH
04/22/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH
04/01/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH
03/04/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.02 GPH
02/05/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	-0.02 GPH
01/08/2024	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH
12/18/2023	1:14 AM
LEAK TEST	0.20 GPH
SLOPE	0.00 GPH

PASSED SCALD TESTS

TANK 1

09/14/2024	7:03 AM
LEAK TEST	0.20 GPH
SLOPE	0.02 GPH
02/23/2024	1:42 AM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH
07/12/2022	2:53 AM
LEAK TEST	0.20 GPH
SLOPE	0.07 GPH

TANK 2

03/17/2023	2:26 AM
LEAK TEST	0.20 GPH
SLOPE	-0.07 GPH

TANK 3

12/22/2024	5:12 PM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH
12/14/2024	11:17 PM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH
11/14/2024	11:06 PM
LEAK TEST	0.20 GPH
SLOPE	0.04 GPH
10/15/2024	8:43 PM
LEAK TEST	0.20 GPH
SLOPE	0.08 GPH
09/15/2024	11:15 PM
LEAK TEST	0.20 GPH
SLOPE	0.04 GPH
08/16/2024	11:39 PM
LEAK TEST	0.20 GPH
SLOPE	-0.07 GPH

07/17/2024	11:47 PM
LEAK TEST	0,20 GPH
SLOPE	0,10 GPH
06/17/2024	7:48 PM
LEAK TEST	0,20 GPH
SLOPE	-0,09 GPH
05/18/2024	6:05 PM
LEAK TEST	0,20 GPH
SLOPE	-0,01 GPH
04/20/2024	9:03 PM
LEAK TEST	0,20 GPH
SLOPE	-0,03 GPH
03/21/2024	10:38 PM
LEAK TEST	0,20 GPH
SLOPE	0,02 GPH
02/20/2024	8:16 AM
LEAK TEST	0,20 GPH
SLOPE	0,07 GPH
01/21/2024	10:26 PM
LEAK TEST	0,20 GPH
SLOPE	-0,09 GPH
12/22/2023	10:23 PM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH
TANK 4	
12/18/2024	11:37 PM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH
12/03/2024	12:22 PM
LEAK TEST	0,20 GPH
SLOPE	-0,02 GPH
11/05/2024	3:40 AM
LEAK TEST	0,20 GPH
SLOPE	-0,00 GPH
10/13/2024	2:41 PM
LEAK TEST	0,20 GPH
SLOPE	-0,00 GPH
09/13/2024	7:28 PM
LEAK TEST	0,20 GPH
SLOPE	-0,01 GPH
08/14/2024	10:43 PM
LEAK TEST	0,20 GPH
SLOPE	-0,01 GPH
07/15/2024	11:38 PM
LEAK TEST	0,20 GPH
SLOPE	-0,03 GPH
06/16/2024	8:47 PM
LEAK TEST	0,20 GPH
SLOPE	-0,03 GPH
05/29/2024	12:37 AM
LEAK TEST	0,20 GPH
SLOPE	-0,03 GPH
04/28/2024	5:24 PM
LEAK TEST	0,20 GPH
SLOPE	-0,05 GPH
04/02/2024	9:38 PM
LEAK TEST	0,20 GPH
SLOPE	-0,00 GPH
03/03/2024	9:27 AM
LEAK TEST	0,20 GPH
SLOPE	-0,02 GPH
02/05/2024	10:10 AM
LEAK TEST	0,20 GPH
SLOPE	-0,01 GPH
01/10/2024	1:50 PM
LEAK TEST	0,20 GPH
SLOPE	0,03 GPH
12/11/2023	9:59 PM
LEAK TEST	0,20 GPH
SLOPE	0,01 GPH