

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL, BY BAB EQUIPMENT

07/04/2024 3:43 PM

LEAK TEST REPORT

UNLEAD 11386, 0 GAL

UNLEAD

END TIME 11:01 PM  
END DATE 06/30/2024  
TEST RESULT ABORTED  
REASON DISPENSE

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL, BY BAB EQUIPMENT

07/04/2024 3:44 PM

LEAK TEST REPORT

UNLEAD 9403, 0 GAL

UNLEAD

END TIME 1:17 AM  
END DATE 07/01/2024  
TEST RESULT ABORTED  
REASON DISPENSE

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL, BY BAB EQUIPMENT

07/04/2024 3:44 PM

LEAK TEST REPORT

PREM 9403, 0 GAL

PREM

END TIME 2:01 AM  
END DATE 07/01/2024  
TEST RESULT ABORTED  
REASON DISPENSE

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL, BY BAB EQUIPMENT

07/04/2024 3:44 PM

LEAK TEST REPORT

DIESEL 3018, 0 GAL

DIESEL

LEAK TEST 0,200 GPH  
LEAK THRESHOLD 0,100 GPH  
CONFIDENCE LEVEL 99, 0%  
TEST STARTED 11:00 PM  
TEST STARTED 06/30/2024  
END TIME 1:14 AM  
END DATE 07/01/2024  
LEVEL 29, 6 IN  
GROSS 1389, 8 GAL  
TEMP 103, 2 F  
TEST RESULT PASSED

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL. BY BAB EQUIPMENT

07/04/2024 3:44 PM

SCALD TEST REPORT

UNLEAD 11386, 0 GAL  
UNLEAD

LEAK TEST 0,200 GPH  
LEAK THRESHOLD 0,100 GPH  
INTERVAL 18,0  
VOL QUALIFY 0,04  
TEST STARTED 11:19 PM  
TEST STARTED 02/15/2024  
STATUS 1000,02  
TEST ENDED 1:42 AM  
TEST ENDED 02/23/2024

SLOPE -0,006 GAL/HR  
TEST RESULT PASSED  
SLOPE EQUALS CALCULATED  
LEAK RATE

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL. BY BAB EQUIPMENT

07/04/2024 3:45 PM

SCALD TEST REPORT

PREM 9403, 0 GAL  
PREM

LEAK TEST 0,200 GPH  
LEAK THRESHOLD 0,100 GPH  
INTERVAL 18,0  
VOL QUALIFY 0,04  
TEST STARTED 8:41 AM  
TEST STARTED 07/04/2024  
STATUS 0,02  
TEST ENDED 1:05 PM  
TEST ENDED 07/04/2024

SLOPE 0,064 GAL/HR  
TEST RESULT PASSED  
SLOPE EQUALS CALCULATED  
LEAK RATE

PRIYA LUCKY EXPRESS  
5307 Western Ave  
South Bend, In  
574-288-9110  
INSTAL. BY BAB EQUIPMENT

07/04/2024 3:45 PM

SCALD TEST REPORT

DIESEL 3018, 0 GAL  
DIESEL

LEAK TEST 0,200 GPH  
LEAK THRESHOLD 0,100 GPH  
INTERVAL 18,0  
VOL QUALIFY 0,04  
TEST STARTED 7:38 PM  
TEST STARTED 06/09/2024  
STATUS 0,02  
TEST ENDED 8:47 PM  
TEST ENDED 06/16/2024

SLOPE -0,028 GAL/HR  
TEST RESULT PASSED  
SLOPE EQUALS CALCULATED  
LEAK RATE