

PRIYA LUCKY EXPRESS
5307 Western Ave
South Bend, In
574-288-9110

INSTAL. BY B&B EQUIPMENT

05/12/2025 9:12 PM

SCALD TEST REPORT

UNLEAD 11386.0 GAL

UNLEAD

LEAK TEST 0.200 GPH

LEAK THRESHOLD 0.100 GPH

INTERVAL 18.0

VOL QUALIFY 0.0%

TEST STARTED 12:03 AM

TEST STARTED 04/25/2025

STATUS 16201.02

TEST ENDED 5:49 AM

TEST ENDED 04/25/2025

SLOPE 0.207 GAL/HR

TEST RESULT INCREASE

SLOPE EQUALS CALCULATED

LEAK RATE

UNLEAD 9403.0 GAL

UNLEAD

LEAK TEST 0.200 GPH

LEAK THRESHOLD 0.100 GPH

INTERVAL 18.0

VOL QUALIFY 0.0%

TEST STARTED 5:54 AM

TEST STARTED 03/15/2025

STATUS 17000.02

TEST ENDED 9:05 AM

TEST ENDED 03/15/2025

SLOPE -0.096 GAL/HR

TEST RESULT PASSED

SLOPE EQUALS CALCULATED

LEAK RATE

PREM 9403.0 GAL

PREM

LEAK TEST 0.200 GPH

LEAK THRESHOLD 0.100 GPH

INTERVAL 18.0

VOL QUALIFY 0.0%

TEST STARTED 4:16 AM

TEST STARTED 05/12/2025

STATUS 0.02

TEST ENDED 6:16 AM

TEST ENDED 05/12/2025

SLOPE -0.002 GAL/HR

TEST RESULT PASSED

SLOPE EQUALS CALCULATED

LEAK RATE

DIESEL 3018.0 GAL

DIESEL

LEAK TEST 0.200 GPH

LEAK THRESHOLD 0.100 GPH

INTERVAL 18.0

VOL QUALIFY 0.0%

TEST STARTED 8:07 AM

TEST STARTED 05/01/2025

STATUS 0.02

TEST ENDED 5:29 PM

TEST ENDED 05/07/2025

SLOPE -0.006 GAL/HR

TEST RESULT PASSED

SLOPE EQUALS CALCULATED

LEAK RATE

PRIYA LUCKY EXPRESS
5307 Western Ave
South Bend, In
574-288-9110

INSTAL, BY B&B EQUIPMENT

05/12/2025 9:12 PM

REGULATORY REPORT

HARDWARE STATUS

TS-CIM	NOT INSTALLED
TS-ROM	NOT INSTALLED
TS-SEM 1	NOT INSTALLED
TS-SEM 2	NOT INSTALLED
TS-CPM	NOT INSTALLED
PRINTER	OPERATIONAL
FAX/MOD	OPERATIONAL

PROBES

PROBE 1	OPERATIONAL
PROBE 2	OPERATIONAL
PROBE 3	OPERATIONAL
PROBE 4	OPERATIONAL

AUXILIARY INPUTS

AUX IN 1	OPERATIONAL
AUX IN 2	OPERATIONAL

PASSED LEAK TESTS

TANK 1

07/04/2016	3:14 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH

TANK 2

02/06/2023	6:59 AM
LEAK TEST	0.20 GPH
SLOPE	0.00 GPH

TANK 3

02/10/2025	2:39 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH

12/16/2024	2:34 AM
LEAK TEST	0.20 GPH
SLOPE	-0.00 GPH

11/25/2024	3:24 AM
LEAK TEST	0.20 GPH
SLOPE	-0.06 GPH

11/11/2024	3:04 AM
LEAK TEST	0.20 GPH
SLOPE	-0.09 GPH

09/16/2024	3:19 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH

08/26/2024	3:19 AM
LEAK TEST	0.20 GPH
SLOPE	0.01 GPH

02/05/2024	3:39 AM
LEAK TEST	0.20 GPH
SLOPE	-0.01 GPH

TANK 4

05/12/2025	12:59 AM
LEAK TEST	0.20 GPH
SLOPE	

PRIYA LUCKY EXPRESS
5307 WESTERN AVE
South Bend, In
574-288-9110
INSTALLED BY DBB EQUIPMENT

05/12/2025 9:13 PM

LEAK TEST REPORT

UNLEAD 11386.0 GAL

UNLEAD

END TIME 11:09 PM
END DATE 05/11/2025
TEST RESULT ABORTED
REASON DISPENSE

UNLEAD 9403.0 GAL

UNLEAD

END TIME 11:00 PM
END DATE 05/11/2025
TEST RESULT ABORTED
REASON DISPENSE

PREM 9403.0 GAL

PREM

LEAK TEST 0.200 GPH
LEAK THRESHOLD 0.100 GPH
CONFIDENCE LEVEL 99.0%
TEST STARTED 11:00 PM
TEST STARTED 05/11/2025
END TIME 4:24 AM
END DATE 05/12/2025
LEVEL 17.0 IN
GROSS 1057.8 GAL
TEMP 56.6 F
TEST RESULT FAILED

DIESEL 3018.0 GAL

DIESEL

LEAK TEST 0.200 GPH
LEAK THRESHOLD 0.100 GPH
CONFIDENCE LEVEL 99.0%
TEST STARTED 11:00 PM
TEST STARTED 05/11/2025
END TIME 12:59 AM
END DATE 05/12/2025
LEVEL 17.6 IN
GROSS 693.4 GAL
TEMP 133.3 F
TEST RESULT PASSED