Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 16476	Contact Number				
Facility Name Sunoco	Contact email				
Address 1911 US HWY 50 E Bedford 47421	Date of Inspection 10/24/2			3	
Operator on Duty Name				Rider	
	erator Train	ing			
Operator Training current	Yes	ONo	OperatorNotified	Yes	Ovo
	tion/Notificat	ion Form		0	0
Is Registration current with correct owner, operator etc.	Yes	O√o	OperatorNotified	Ves	Oıo
	elease Detecti	_		_	
Release Detection Method	√ ATG	C IM	SIR	OIC	Other
Make and Model	VR	TLS-35			
Does it have paper?	Yes	O _{No}	OperatorNotified	Yes	\bigcirc to
Is it in Alarm mode?	Yes	\bigcirc No	OperatorNotified	OYes .	Olo
Interstitial Monitoring Sensor Status Normal	Yes	Olo	OperatorNotified	Yes	Ovo
Necessary Monthly Printout Taken	Yes	ON _o	OperatorNotified	Yes	No
	Spill Buckets	minim	٥(
Are Spill Buckets Clean and free from water, debris, product etc?	O/es	(S) No	Operator Notified	(V)es	No
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	No
	Fill Ports	0			
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	O ₁ o	OperatorNotified	Tes	No
	ping/STP Sur				
Are Sumps Clean and free from water, debris, product etc?	OYes .	Olo	OperatorNotified	Ves	No
Under Dispe	nser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	⊘ √o	OperatorNotified	(V) Yes	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF.	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tankso	sdata@gmail.com			www.tanksdata.com	
talikst	ana (eginan, c	OIII			202