

30 DAYS WALK THROUGH INSPECTION

000
Tanks Data

UST Facility I.D. (FID) #	16476	Contact Number	
Facility Name	SUNOCO	Contact email	
Address	1911 US Hwy 50 E, Bedford,	Date of Inspection	12/10/24
Operator on Duty Name	IN 47421	Name of the Person Conducting Inspection	AKSM7

Operator Training current	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is Registration current with correct owner, operator etc.	Registration/Notification Form		☐ Yes	☐ No	Operator Notified
Release Detection Method	Release Detection		☒ ATG	☐ DIM	☐ BIR
Make and Model	LR TLS 350		☐ IC	☐ Other	
Does it have paper?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is it in Alarm mode?	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Necessary Monthly Printout Taken	☐ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes	☐ No	Operator Notified	☐ Yes	☐ No
Are Sumps Clean and free from water, debris, product etc?	Pipe/STP Sumps		☒ Yes	☐ No	Operator Notified
Are UDCs clean and free from water, debris, product etc?	Under Dispenser Containments (UDC)		☐ Yes	☒ No	Operator Notified

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name: 317-645-0215
Signature: tanksdata@gmail.com
Date: www.tanksdata.com