

0011
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (RTD) #	16476	Contact Number	
Facility Name	SUNOCO	Contact email	
Address	1911 USTHUR 50 E, Redford	Date of Inspection	07/03/24
Operator on Duty Name	IN 47421	Name of the Person Conducting Inspection	AKSHIT SHARMA

Operator Training current

Operator Training

Operator Notified Yes No

Is Registration current with correct owner, operator etc.

Registration/Notification Form

Operator Notified Yes No

Release Detection Method

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Release Detection

Operator Notified Yes No

MTG LR 725 350' SIR PRINTER NOT WORKING

Spill Buckets

Are Spill Buckets Clean and free from water, debris, product etc?

Operator Notified Yes No

Are the Spill Bucket in good condition and free of damage/cracks

Operator Notified Yes No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Operator Notified Yes No

Are Sumps Clean and free from water, debris, product etc?

Operator Notified Yes No

Are UDCs clean and free from water, debris, product etc?

Operator Notified Yes No

Operator on Duty Name

317-645-0215

tankdata@gmail.com

Signature

Date

www.tankdata.com

20220516