

001

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (PID) # 16476		Contact Number
Facility Name SENE		Contact email
Address 1911 US Hwy 50E, Bedford, VA		Date of Inspection 11/05/24
Operator on Duty Name 47421		Name of the Person Conducting Inspection AKSHIT
Operator Training current		Operator Training
Is Registration current with correct owner, operator etc.		Registration/Notification Form
Release Detection Method		Release Detection
Make and Model		VATG 1127 L5350
Does it have paper?		Yes
Is it in Alarm mode?		Yes
Interstitial Monitoring Sensor Status Normal		Yes
Necessary Monthly Printout Taken		Yes
Are Spill Buckets Clean and free from water, debris, product etc?		Spill Buckets
Are the Spill Bucket in good condition and free of damage/cracks		Yes
Is Fill pipe cap tight and fill pipe free from any obstruction?		Fill Ports
Are Sumps Clean and free from water, debris, product etc?		Pipeline/STP Sumps
Are UDCs clean and free from water, debris, product etc?		Under Dispenser Containments (UDC)
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.		Operator/Notified
Operator on Duty Name		Signature
317-645-0215		Date
tanksdata@gmail.com		www.tanksdata.com