

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) #	16479	Contact Number	
Facility Name	SN 010	Contact email	
Address	1911 US HWY 50 E Bedford, IN	Date of Inspection	06/01/24
Operator on Duty Name	47421	Name of the Person Conducting Inspection	AKSHIT SAHARAN

Operator Training current

Operator Training

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Registration/Notification Form

Is Registration current with correct owner, operator etc.

☐ Yes ☐ No

Operator Notified

☐ Yes ☐ No

Release Detection Method

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

Release Detection

☒ MTG ☐ CIM

Operator Notified

☐ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

Spill Buckets

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

☒ Yes ☐ No

Operator on Duty Name

317-645-0215

tanksdata@gmail.com

www.tanksdata.com

20220516

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Signature

Date

PRINTER NOT WORKING