Tanks Data	TO ME THE OWNER OF THE PROPERTY OF THE PROPERT		
UST Facility I.D.((FID) # 16476	Contact Number		
Facility Name SUNOCO	Contact email		
Address 1911 US HWY SOE BEDFORD 47421	Date of Inspection 04/	66/24	
Operator on Duty Name	Name of the Person Conducting Inspection	M TH BUHS	
Operator Training current		OperatorNotified (Yes Oto
Is Registration current with correct owner, operator etc.	Corm	OperatorNotified (Q _a
Release Detection Method	ATG CIM	O REC	
Make and Model	7		
Does it have paper?	Ores On	OperatorNotified (O _o
Is it in Alarm mode?	O Sea	OperatorNotified (
Interstitial Monitoring Sensor Status Normal	ģ	OperatorNotified (Ş
a new processory of a strangents a suspension of the strangents	Spill Buckets PRI	PRINTER NOT W	DRKING & OKE
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Ö Ö	OperatorNotified (ĈÔ.
Is Fill pipe cap tight and fill pipe free from any obstruction?	Piping/STP Sumps	OperatorNotified (o o
Are Sumps Clean and five from water, debris, product etc? Under Disper		OperatorNotified (Oran Quo
Are UDCs clean and free from water, debris, product etc?	Que Que	OperatorNotified (Q _e
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.	S OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING I FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.	EXISTING RULES AN	D REQULATIONS
Operator on Duty Name	Signature	п	Date
317-645-0215 tanksd	tanksdata@gmail.com	W	www.tanksdata.com