

001
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) # 16476.

Contact Number

Facility Name SURECO

Contact email

Address 19111 US HWY 50E, Bedford, VA

Date of Inspection 09/10/14

Operator on Duty Name

47421

Name of the Person Conducting Inspection AKSMIT

Operator Training current

Operator Training
☐ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☐ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Release Detection Method

Release Detection
☒ MFG ☐ CIM
VR TLS 350

☐ SIR

☐ IC

☐ Other

Make and Model

Does it have paper?

Is it in Alarm mode?

☒ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

☒ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Spill Buckets

☐ Yes ☒ No

Operator Notified

☒ Yes

☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes

☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☒ Yes

☐ No

Fill Ports

☒ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes ☐ No

Operator Notified

☐ Yes

☐ No

Piping/STP Sumps

☒ Yes ☐ No

Operator Notified

☒ Yes

☐ No

Are Sumps Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes

☐ No

Are UDCs clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes

☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com