

30 DAYS WALK THROUGH INSPECTION

Tanks Data

UST Facility I.D. (FID) # 16478

Contact Number

Facility Name SUNOCO

Contact email

Address 1911 US Hwy 50E, Bedford

Date of Inspection 8/12/25

Operator on Duty Name

1647421

Name of the Person Conducting Inspection

AKSHIT

Operator Training current

☐ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Is Registration current with correct owner, operator etc.

☐ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Release Detection

Release Detection Method

Make and Model

Does it have paper?

Is it in Alarm mode?

Interstitial Monitoring Sensor Status Normal

Necessary Monthly Printout Taken

☒ ATG

☐ CIM

☐ SIR

☐ IC

☐ Other

VRTLS350

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

☐ Yes

☒ No

Operator Notified

☐ Yes

☐ No

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

☐ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Spill Buckets

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Fill Ports

☒ Yes

☐ No

Operator Notified

☐ Yes

☐ No

Piping/STP Sumps

☒ Yes

☐ No

Operator Notified

☒ Yes

☐ No

Under Dispenser Containments (UDC)

☒ Yes

☐ No

Operator Notified

☒ Yes

☐ No

☐ Yes

☒ No

Operator Notified

☒ Yes

☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tanksdata@gmail.com

www.tanksdata.com

PRINTER
IS NOT
PRINTING