



5296 Breakers Way, Carmel, IN 46033

 www.tanksdata.com
 tanksdata@gmail.com
 (317)-300-6065

Date

8/11/25

LEAK DETECTOR TEST (DATA SHEET)

Test Location Information

Name	FID 16476
Address	1911 US 50
City	Bedford, IN, 47421
Phone	
Contact	

Technician Information

Name	Josh Rider
Cert #	UC202406986

TYPE OF LEAK DETECTOR

PRODUCT TYPE	MAKE	MODEL	SERIAL#
Reg	Red Jacket MLLD		
Prem	Red Jacket MLLD		
Dies	Red Jacket MLLD		

Pump #	PRODUCT TYPE	Pump Pressure	Functional Element Holding PSI	Resiliency	Test Leak Rate ML/MIN	Opening Time	Pass/Fail
1	Regular	26	15	70 ml	189ml	1 sec	Pass 
2	Premium	28	16	110 ml	189ml	2 sec	Pass 
3	Diesel	31	21	190 ml	189ml	3 sec	Pass 
4					189ml		. 
5					189ml		. 
6					189ml		. 
7					189ml		. 
8					189ml		. 

Comment:

All three lines required extra bleeding before would go into slow flow. However, all three did go into slow flow.

Technician Signature :

