

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
\boxtimes	tanksdata@gmail.com
0	(317)-300-6065

Date

8/11/25

	TATIO (eblii bii	NITECOL	TY TEST
T I DKU	SIAIIC	SPILL DU	INIEGR	II Y IEƏI

SINGLE- AND DOUBLE-WALLED VACUUM TEST METHOD

Facility Name: Sunoco					Owner: HELEE FOUR IN					R INC	
Address: 1911			Address: 1911 US 50								
City, State, Zip Code: Bedford,		-	City, State, Zip Code: Bedford, IN, 47421								
Facility I.D. #: 16476					Phone #:						
This procedure is to test the leak integrity of sir 6.3 for single-walled vacuum test method and								.2 f	or hydrostatic te	est method	, Section
Tank Number	1		2		3						
Product Stored	Regular		Premium	m Diesel							
Spill Bucket Capacity	5 gal		5 gal	I 5 gal							
Manufacturer	OPW		OPW		OPW						
Construction	sw	•	sw	•	sw	•].	•].	~
Test Type	Hydrostati	lacksquare	Hydrostati	_	Hydrostati].	•		<u>]</u> .	•
Spill Bucket Type	Product	•	Product	•	Product	•		•		<u> </u>	_
Liquid and debris removed from spill bucket?	Yes	•	Yes	•	Yes	•		•		<u>]</u> .	•
Visual Inspection (No cracks, loose parts or separation of the bucket from the fill pipe.)	Pass	•	Pass	•	Pass	~		•			-
Tank riser cap included in test?	Yes	•	Yes	•	Yes	•].	•			~
Drain valve included in test?	Yes	•	N/A	•	N/A	•		•			~
Starting Level	11.5"		13.5"		13.5"						
Test Start Time	1:45pm		2:00pm		2:05pm						
Ending Level	11.5"		13.5"	13.5"							
Test End Time	2:45pm		3:00pm		3:05pm						
Test Period	1 Hr		1 Hr		1 Hr						
Level Change	0		0		0						
Pass/fail criteria: Must pass visual inspection. Hydrostatic: Wate at least 12 inches water column	er level drop of les	s tha	ın 1/8 inch; Vacuu	ım s	single-walled only	: Mai	intain at least 26 incl	nes v	vater column; Vacuur	n double-walle	ed: maintain
Test Results	Pass	•	Pass	•	Pass	•].	•	. [<u>]</u> .	~
Comments:								\			
Tester's Name :	sh Rider			T	ester's S	ig	nature :				