	3	30 DAYS W	ALK THROUGH	INSPEC	TION
Tanks Data					
UST Facility I.D.((FID) # 7 830	Contact Number				
Facility Name Millipe 66	Contact email				
Address 70 2 Un Colmany F 46661	Date of Inspection $69-11-767$				
Operator on Duty Name	Name of the Person Conducting Inspection Cryslagot				
Op	erator Train				
Operator Training current	Yes	ONo	OperatorNotified	()Yes	(No
Is Registration current with correct owner, operator etc.	ion/Notifica	tion Form	OperatorNotified	Ores	Oio
[일하는 기원 경기 전경 경기 전경 기원	lease Detect	ion			
Release Detection Method	MATG	CIM	SIR	OIC	Other
Make and Model URTCS-4	50				
Does it have paper?	Yes	No	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Oio
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Olio
Necessary Monthly Printout Taken	Yes	ONo	OperatorNotified	O'es	Oio
	Spill Bucket	S			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	Oio
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	Oio
	Fin Ports				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	No	OperatorNotified	()es	Olo
를 보면 있는데 보고 있는데 하면 가는데 하면	ping/STP Su	mps			
Are Sumps Clean and free from water, debris, product etc?	Yes	()No	OperatorNotified	Ves	Olo
		ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	(D'es	Oio
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF CEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksdata@gmail.com				www.tanksdata.com	
					20220516