	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)#, 7 47/)	Contact Number				
Facility Name Dhi 4011286	Contact Number Contact email				
Address 262 Limble nury E46661	Date of Inspection 10 - 17 - 707 S				
Operator on Duty Name	Name of the Pers	aparel (applications) the same of the same of			
	Conducting Inspe		Juggero	el	
Op	erator Training				
Operator Training current	Yes C	No (OperatorNotified	Yes	(No
[[[[[[[]]]] [[[[]]] [[[]] [[[]]] [[[]] [tion/Notification E	1			
Is Registration current with correct owner, operator etc.	Yes (No (OperatorNotified	Ves	ONO
	elease Detection	W.		O	<u> </u>
Release Detection Method	AIG	XIM	SIR	Oic	Other
Make and Model Does it have paper?	5 Wes	No	OperatorNotified	Yes	\bigcirc
Is it in Alarm mode?	Yes		OperatorNotified	\times	X
	X. >	<		Xes	X.º
Interstitial Monitoring Sensor Status Normal	Xes C		OperatorNotified	Yes	No.
Necessary Monthly Printout Taken	Ures ()NO	OperatorNotified	Yes	ONO
	Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes C		OperatorNotified	es	Oio
Are the Spill Bucket in good condition and free of damage/cracks	Yes C	No	OperatorNotified	Ces	Olo
	Kill Ports				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes (No	OperatorNotified	Oes	Olo
수 없는 사람들이 되었는데 보고 있는데 보고 있는데 되었는데 되었는데 되었는데 되었는데 되었는데 되었다. 그런데 이번에 이번에 되었는데 되었는데 이번에 되었는데 되었는데 되었는데 되었는데 되었는데 되었는데 되었는데 되었는데	ping/STP Sumps				
Are Sumps Clean and free from water, debris, product etc?	Yes &	who were	OperatorNotified	Yes	Olo
	enser Containment				
Are UDCs clean and free from water, debris, product etc?	OYes 6	No	OperatorNotified	O es	(No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF ACCO	ORDING TO	EXISTING RULES	AND REQULA	ATIONS
Operator on Duty Name		ignature		Date	
317-645-0215 tanks	data@gmail.com	/	5	www.tanksdat	ta.com
					2022