Tanks Data	30 DAYS WALK THROUGH INSPECTION						
UST Facility I.D.((FID) # 7 330	Contact Number						
Facility Name Phillips 66	Contact email						
Address 707 him Annay F 46601	Date of Inspection 06-12-2025						
Operator on Duty Name	Name of the Person Conducting Inspection Greens acct						
0	perator Train		1				
Operator Training current	Yes	No	OperatorNotified	Yes	ONO		
Registra	ation/Notificat	tion Form			0.		
Is Registration current with correct owner, operator etc.	Yes	O _{No}	OperatorNotified	Ves	O40		
	telease Detecti	ion		Orc	Other		
Release Detection Method	ATG	CIM	SIR	Oic	Other		
Make and Model URTLS -54	30			<u> </u>			
Does it have paper?	Yes	ON ₀	OperatorNotified	Yes	200		
Is it in Alarm mode?	Yes	O _N o	OperatorNotified	Yes	Q^{10}		
Interstitial Monitoring Sensor Status Normal	Yes	O _V o	OperatorNotified	Yes	Oyo		
Necessary Monthly Printout Taken	Yes	ON _o	OperatorNotified	Yes	Ovo		
	Spill Buckets	s					
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(P)No	OperatorNotified	es	O40		
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	O40		
	Fill Ports	_		~			
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Olo		
	iping/STP Sur	mps		_			
Are Sumps Clean and free from water, debris, product etc?	Yes	Oylo	OperatorNotified	Ves	\bigcirc		
Under Dispe	enser Contain	ments (UDC)		_			
Are UDCs clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	res	Olo		
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.			2	
Operator on Duty Name		Signature		Date 0	6-12-20	1	
: Handelle - Handelle	data@gmail.c	om July		www.tanks	data.com 20220516	6	