Tanks Data	30 DAYS WALK THROUGH INSPECTION				
JST Facility I.D.((FID) # 15434	Contact Number				
facility Name Phillips 66	Contact email				
Address 14992 SR-23 E Granger 46530	Date of Inspection 7/17/23				
Operator on Duty Name					
-		Name of the Person $Conducting Inspection$			
	erator Train	ning			
Operator Training current	Yes	\bigcirc No	OperatorNotified	OYes .	\bigcirc No
Registrat	ion/Notifica	tion Form		~	_
Is Registration current with correct owner, operator etc.	Yes	. ONO	OperatorNotified	Ves	Oto
Release Detection Method	lease Detect	_	_	_	_
Make and Model	⊘ ATG	O EIM	SIR	O_{IC}	Other
	VR	TLS-49		_	\sim
Does it have paper?	Yes	\bigcirc No	OperatorNotified	Yes	\bigcirc 10
Is it in Alarm mode?	Yes	O_{N^0}	OperatorNotified	⊘ Yes	Oto
Interstitial Monitoring Sensor Status Normal	O'es	\bigcirc No	OperatorNotified	Ores	Ovo
Necessary Monthly Printout Taken	Yes	\bigcirc No	OperatorNotified	Yes	No
	Spill Bucket	ts			
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	(V)No	OperatorNotified	(Ves	Oko
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	\bigcirc No	OperatorNotified	Ces	No
	Fill Ports	0			0.0
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	\bigcirc No	OperatorNotified	(Tes	Olo
	oing/STP Su			_	0
Are Sumps Clean and free from water, debris, product etc?	Yes	\bigcirc 10	OperatorNotified	(V)res	No
	nser Contain	nments (UDC)			0
Are UDCs clean and free from water, debris, product etc?	Yes	\bigcirc No	OperatorNotified	(V)res	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tankso	ssdata@gmail.com			www.tanksdata.com	