

5296 Breakers Way, Carmel, IN 46033

	www.tanksdata.com
\boxtimes	tanksdata@gmail.com
3	(317)-300-6065

Date

3/6/25

UST Annual Walkthrough Inspection

1. UST Facility Information												
Facility I.D. #:	10566											
UST Facility Name	Expo Amoco											
UST Facility Physical Address	Street Address :	5316 W Western Ave	City:	South Bend	Zip Code :	IN, 46619						

2. Annual Inspection Checklist

Category	Description		N/A	Tank 1		Tank 2		Tank 3		Tank4 Dies2		Tank 5		Tank 6		Tank 7	Tank 8	
				Reg		Prem		Dies1		Dies	52	_						
	Cap in good condition, seals tightl probe wire goes through	y, hole sealed where		Yes	_	Yes	•	Yes	•	Yes	•		1	•		•] .	•
ATG Manhole	Junction box has cover, not corroc wiring in good condition	led; intrinsically safe		Yes	•	Yes	•	Yes	•	Yes	•	. [-		•		•
ATO MUNICIPAL	Manhole cover in good condition			Yes	•	No	•	Yes	•	Yes	•		1	-		•		•
	Functionality Test Date :	3/6/25		•	•	•	•		•		•	. [-	-		•		•
	Single-walled spill containment m tested within last 3 years	anhole tightness		Yes	•	Yes	•	Yes	•	Yes	•		-	•].	•		•
	Double-walled spill containment r tested within last 3 years OR inspe		~		•		•	-	•		•	. [1	•		•	<u> </u>	•
Spill Bucket	Are spill buckets free of product, w	ater and debris ?		Yes	•	Yes	•	Yes	•	Yes	•			-		•].	•
	Are spill buckets free of damage/c	racks?		Yes	•	Yes	•	Yes	•	Yes				•		•].	•
	HSB Test Date :	6/30/22			•		•		•	•	•	. [-	-		•] -	•
	Drop tube shutoff valve passes ins corrosion not present	pection & excessive		Yes	•	Yes	•	Yes	•	Yes	V			•		•		•
Overfill	Ball float valve passes inspection, excessive corrosion not present	can be removed &	~		•		•	-	•		•		1	•		•	-	•
Prevention	Overfill alarm passes inspection		~	•	▼		•	<u>. [</u>	•	•	•	ļ. [•	·].	V	<u> </u> -	V
	OPV Test Date :	6/30/22			•		•		•		•		•	•		•	<u> </u>	•
Corrosion Protection	Galvanic Cathodic Protection test within the past 3 years and the tes		V		•		•		•		•			·		•		•
	Impressed Current Cathodic Prote conducted within the past 3 years		~		•		•		•		•		•	·		•		•
	Tank Lining inspected as required	and in good condition	~		•		•	. [•		•	. [1	•		~		•
	CP Test Date :		V		•		•		•		•	. [-	•		•		•

Category	Description		N/A Tank		Tank 2		Tank 3		Tank4		Tank 5	Tank 6	Tank 7	Tank 8	
			Reg	Reg		m	Dies1		Dies	s2					
	12 Months of RD printed and on site		Yes	lacksquare	Yes	•	Yes	V	Yes	•			. 🔽	. 🔽	
	Release Detection Report have issues in past months		No	lacksquare	No	lacksquare	No	V	No	•				. 🔽	
Release Detection	ATG console has any history of alarm in past months		No	lacksquare	No	lacksquare	No	•	Yes	•				. 🔻	
	Release Detection Type : ATG			•		•		•		•					
	Liquid and debris removed from sump?		Yes	T	Yes	lacksquare	Yes	•	Yes	▼					
Containment Sumps	Are containment sumps free of damage/cracks?		Yes	•	Yes	•	Yes	•	Yes	•			. 🔻		
	HSC Test Date :	~	•	•	•	•		•		•					
Stage I Testing	Verify that Stage I testing has been conducted and test results are passing	~						•		•					
		<u>'</u>							•						
Comments/I															
Name (Class A & B	Operator) :														
Name (Person cond						Josh	Ric	der							
Signature (Person o	\ \														