

TRIENNIAL INSPECTION

Facility Name: MAE'S MART /ABISIBI FOOD MART Test Date: 04/29/2025

Facility Address: 3204 MONROE STREET LA PORTE IN 46350

Facility ID: 24742

OVERFILL PREVENTION EQUIPMENT INSPECTION

Tank ID #	T1	T2				
Product	RUL	PUL				
Tank Volume (gallons)	9696	9696				
Tank Diameter (Inches)	91	91				
Calculated 90% Level (Inches)	76	76				
Calculated 95% Level (Inches)	81	81				

Automatic Shutoff Device (Flapper Valve) Inspection

Measured Shutoff Level (Inches)	76	81				
Drop tube removed from tank?	YES	YES				
Drop tube and float mechanism free of debris?	YES	YES				
Float moves freely and poppet moves into flow path?	YES	YES				
Bypass valve in drop tube open and unblocked?	N/A	N/A				
Flapper valve adjusted to shut off flow at 95% capacity?	No	YES				
INSPECTION RESULT	PASS	PASS				

Overfill Alarm Inspection

Electronic device and probe operating properly?						
Alarm activates at 90% of tank capacity?						
Alarm is heard and seen from tank fueling area?						
INSPECTION RESULT						

Comments

The PUL ball float was removed. Drop tube set to 95%
 The RUL ball float was not removed. Drop tube set to 90%

Technician Name: Seamus Polanski

Dispatch # 7577

B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19