

30 DAYS WALK THROUGH INSPECTION

000
Tanks Data

UST Facility I.D. (FID) # 24792

Contact Number

Facility Name MARRATHON

Contact email

Address 3204 Monrovia, LaPorte,

Date of Inspection 01/16/25

Operator on Duty Name

1246350

Name of the Person Conducting Inspection AKHIT

Operator Training current

Operator Training

Operator Notified

Yes

No

Is Registration current with correct owner, operator etc.

Registration/Notification Form

Operator Notified

Yes

No

Release Detection Method

Release Detection

Operator Notified

Yes

No

Make and Model

ATG VR TIS350

Operator Notified

Yes

No

Does it have paper?

Yes

No

Operator Notified

Yes

No

Is it in Alarm mode?

Yes

No

Operator Notified

Yes

No

Interstitial Monitoring Sensor Status Normal

Yes

No

Operator Notified

Yes

No

Necessary Monthly Printout Taken

Yes

No

Operator Notified

Yes

No

Spill Buckets

Yes

No

Operator Notified

Yes

No

Are Spill Buckets Clean and free from water, debris, product etc?

Yes

No

Operator Notified

Yes

No

Are the Spill Bucket in good condition and free of damage/cracks

Yes

No

Operator Notified

Yes

No

Fill Ports

Yes

No

Operator Notified

Yes

No

Is Fill pipe cap tight and fill pipe free from any obstruction?

Yes

No

Operator Notified

Yes

No

Piping/STP Sumps

Yes

No

Operator Notified

Yes

No

Are Sumps Clean and free from water, debris, product etc?

Yes

No

Operator Notified

Yes

No

Under Dispenser Containments (UDC)

Yes

No

Operator Notified

Yes

No

Are UDCs clean and free from water, debris, product etc?

Yes

No

Operator Notified

Yes

No

Operator on Duty Name

317-645-0215

Signature

tanksdata@gmail.com

Date

www.tanksdata.com