

TRIENNIAL INSPECTION

Facility Name: MAE'S MART /ABISIBI FOOD MART Test Date: 05/06/2025
Facility Address: 3204 MONROE STREET LA PORTE IN 46350
Facility ID: 24742

UST CONTAINMENT SUMP INTEGRITY TESTING: HYDROSTATIC

Test Type/Reason: Repair

Sump Name	RUL STP				
Clean of liquid/debris	YES				
VISUAL INSPECTION	PASS				
Test Start Time	1:00				
Test End Time	2:00				
Starting Water Level (in)	27				
Ending Water Level (in)	27				
Water Level Change (in)	0				
TEST RESULT	PASS				

Sump Name					
Clean of liquid/debris					
VISUAL INSPECTION					
Test Start Time					
Test End Time					
Starting Water Level (in)					
Ending Water Level (in)					
Water Level Change (in)					
TEST RESULT					

Comments

--

Technician Name: Seamus Polanski

Dispatch # 7577

B&K Equipment completes testing and inspections per recommended practices of PEI RP1200-19