Tanks Data	3	0 DAYS W	ALK THROUGH	INSPEC	TION
UST Facility I.D.((FID)# 7477	Contact Number				
Facility Name /5 /	Contact email				
Address 3 704 Moonsoof 46750	Date of Inspection 19-14-78 25				
Operator on Duty Name	Name of the Person Conducting Inspection Gurbret				
Or	perator Train				
Operator Training current	Oyes	ONO	OperatorNotified	Yes	ONo.
Is Registration current with correct owner, operator etc.	tion/Notificat	(No	OperatorNotified	Ores	Oio
Release Detection Method	elease Detection	on Sim	OSIR	Orc	Other
Make and Model $VV(1)$	Duna	No	OperatorNotified	Yes	\bigcap
Does it have paper? Is it in Alarm mode?	Yes	Sio	OperatorNotified	Yes	No.
	Yes	K	OperatorNotified	No.	X.
Interstitial Monitoring Sensor Status Normal	Cycs	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Spill Buckets		o per montro di la	000	
	Yes	No	OperatorNotified	Oles	Ovo
Are Spill Buckets Clean and free from water, debris, product etc? Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	Tes	XI.
Are the Spin Bucket in good condition and free or damage, cracks	Fill Ports			0.	
Is Fill pipe cap tight and fill pipe free from any obstruction?	()Yes	(No	OperatorNotified	()es	()io
하다면 가게 되었다면 하다면 하다면 하다면 하는데 하는데 되는데 되는데 되는데 되는데 되는데 되는데 되는데 되는데 하는데 하는데 되었다. 그렇게 되는데 하는데 하는데 하는데 되었다. 그렇게 되었다.	ping/STP Sun	nps			
Are Sumps Clean and free from water, debris, product etc?	Ores	No	OperatorNotified	Yes	(No
Under Disper	nser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Ores	No	OperatorNotified	Pes	Oio
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC	OSSED OFF A	ACCORDING CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	ILATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksd	tanksdata@gmail.com			www.tanksdata.com	
		\ /			202205