Tanks Data	30 DAYS WALK THROUGH INSPECTION					
UST Facility I.D.((FID) # 2 477	Contact Number					
Facility Name Mary thou	Contact email					
Address 3 204 Manage 5+46 350	Date of Inspection $02-05-2075$					
Operator on Duty Name	Name of the Person Conducting Inspection Cruzbacet					
Op	erator Train					
Operator Training current	Yes	No	OperatorNotified	Yes	ONo	
Registrat	ion/Notifica	tion Form		_		
	Yes	ÛN ₀	OperatorNotified	Ves	Olo	
	lease Detecti	ion				
Release Detection Method	CATG	CIM	SIR	Oic	Other	
Make and Model UR TCS - 75	0					
Does it have paper?	Yes	ON ₀	OperatorNotified	Yes	Olo	
Is it in Alarm mode?	Yes	ON ₀	OperatorNotified	Yes	Oio	
Interstitial Monitoring Sensor Status Normal	Yes	ONo	OperatorNotified	Yes	Ovo	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	O'es	Olo	
	Spill Bucket	s				
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	(C)es	Olo	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	No	
	Fill Ports					
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Oio	
	oing/STP Sur	mps		•		
Are Sumps Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Tes	Olo	
Under Disper	nser Contair	nments (UDC)				
Are UDCs clean and free from water, debris, product etc?	Yes	ONO	OperatorNotified	Yes	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF CEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.			
Operator on Duty Name		Signature		Date 07	2-05- 703	
	lata@gmail.c	om		www.tanks	data.com	
					20220516	