Tanks Data	30 DAYS WALK THROUGH INSPECTION
ST Facility I.D.((FID) # 7 4 2 4 7	Contact Number
acility Name Margathan	Contact email
ddress 2709 Monroe St. 96350	Date of Inspection $06-13-7025$
perator on Duty Name	Name of the Person Conducting Inspection Guebacet
Op	perator Training
Operator Training current	Oyes ONo OperatorNotified Oyes ONo
하다[14] 내용하면 하다 [14] 내내 내내 내내 내내 내내 내 내 내내 내내 내내 내내 내내 내내 내	ation/Notification Form
Is Registration current with correct owner, operator etc.	Oyes No OperatorNotified Ves No
	Release Detection
Release Detection Method	OATG OIM OSIR OIC Other
Make and Model VRT25-350	
Does it have paper?	OYes ONo OperatorNotified OYes
Is it in Alarm mode?	Yes ONo OperatorNotified Yes ONO
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified Yes No
Necessary Monthly Printout Taken	Eyes No Operator Notified Yes No
	Spill Buckets
Are Spill Buckets Clean and free from water, debris, product etc?	? Ores Operator Notified Oes Oo
Are the Spill Bucket in good condition and free of damage/cracks	s Oyes No Operator Notified Oes No
Are the Spin Bucket in good condition and	Fill Ports
Is Fill pipe cap tight and fill pipe free from any obstruction?	Ores No OperatorNotified Oes No
P	Piping/STP Sumps
Are Sumps Clean and free from water, debris, product etc?	Ores Olo OperatorNotified Ores Olo
Under Disp	spenser Containments (UDC)
Are UDCs clean and free from water, debris, product etc?	OYes Dio OperatorNotified & Yes No
MOTE, ALL LIQUID/DEPRIS OF WASTE MUST BE DIS	SPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS PROCEDUE BY A CERTIFIED CONTRACTOR.
Operator on Duty Name	Signature Date 00 -/ 5 - CO
[발발 : [발발 : 10] [the left]	nksdata@gmail.com