Tanks Data	30 1	DAYS W	ALK THROUG	HINSPEC	CTION	
UST Facility I.D.((FID)# 1746)	Contact Numb	Contact Number				
Facility Name 1 10 0 16	Contact email					
Address 3 30/ Portag A/ 46672	Date of Inspec		-77-70	375		
Operator on Duty Name	Name of the Po	erson	Gul 3 m	_		
0	perator Training					
Operator Training current	Oyes (	No	OperatorNotified	Yes	ONo	
	tion/Notification	Form		_	_	
Is Registration current with correct owner, operator etc.	OYes (	No	OperatorNotified	Yes	Olo	
	elease Detection					
Release Detection Method	ATG (	CIM	SIR	OIC	Other	
Make and Model V / 1 < 5 _	-72 ×					
Does it have paper?	OYes (	No	OperatorNotified	Yes	Olo	
Is it in Alarm mode?	Yes (	No	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal	Cyces (	No	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	Yes	No	
	Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Ores C	7No	OperatorNotified	Oes	Ovo	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No	OperatorNotified	es	X <sub>0</sub>	
	Fill Ports				0.0	
Is Fill pipe cap tight and fill pipe free from any obstruction?	O'res (	No	OperatorNotified	Tes	Olo	
	ing/STP Sumps					
Are Sumps Clean and free from water, debris, product etc?	Oyes (	ONO .	OperatorNotified	() Yes	No	
	ser Containment	s (UDC)				
Are UDCs clean and free from water, debris, product etc?	OYes C	No	OperatorNotified	Ores	No	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC	SSED OFF ACCO	ORDING TO	EXISTING RULES A	AND REQUL	ATIONS	
		gnature		Date Of-	77	2 -
Operator on Duty Name 317-645-0215 tanksda	ta@gmail.com ≤	2		www.tanksda	27 - 2 ta.com	186
					2022	0516