	30	DAYS WA	LKTHROUGH	INSPEC	TION	
Tanks Data	T.C	la a a				
ST Facility I.D.((FID)# 13992	Contact Number					
acility Name Pillelei 60	Contact email					
1 ddress 372 1 168/1090 Ave 46623	Date of Inspection () 7-79 - 207					
Operator on Duty Name	Name of the Person Conducting Inspection					
Op	erator Train	ing		O.	0	
Operator Training current	Yes	()No	OperatorNotified	Yes	CNO	
Registration current with correct owner, operator etc.	tion/Notificat	ion Form	OperatorNotified	Ores	Oio	
Re	elease Detect	ion				
Release Detection Method	ATG	CIM	SIR	OIC	Other	
Make and Model VRTLS-35	50					
Does it have paper?	Yes	ONo	OperatorNotified	Yes	Oto	
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Ores	Ovo	
Necessary Monthly Printout Taken	Yes	ON0	OperatorNotified	Ores	Oıo	
	Spill Bucke	ts				
Are Spill Buckets Clean and free from water, debris, product etc?	Ves	(a)No	OperatorNotified	es	010	
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ONo	OperatorNotified	es	Olo	
	Fill Ports					
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ONO	OperatorNotified	Oes	Olo	
	piping/STP St	umps		0		
Are Sumps Clean and free from water, debris, product etc?	Yes	(A)No	OperatorNotified	Yes	Oyo	
The state of the s	enser Conta	inments (UDC	2)			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	Olo	
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR				_		
Operator on Duty Name		Signatur	E.	Date /	37-29-20	
317-645-0215 tank	sdata@gmail.com			www.tank	www.tanksdata.com	