Tanks Data	30 DAYS WALK THROUGH INSPECTION				
IST Facility I.D.((FID) # 166.25	Contact Number				
acility Name Amoco	Contact email				
Address 8498 US-6 & 35 Hamlet 46532	Date of Inspection 2/9/24				
Operator on Duty Name	Name of the Person Conducting Inspection Josh Ri			der	7
Op	erator Traini	ng			
Operator Training current	Oyes	No	OperatorNotified	Yes	No
Registra	tion/Notificat	on Form		_	_
Is Registration current with correct owner, operator etc.	Yes	O ₁ o	OperatorNotified	()res	Olo
	elease Detection	on _			_
Release Detection Method	ATG	CIM	SIR	()IC	Other
Make and Model	Auto St	ik JR-2			
Does it have paper?	Yes	ON₀	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Yes	O\o
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	\mathcal{O}_{V_0}
Necessary Monthly Printout Taken	Yes	\sim No	OperatorNotified	Yes	No
	Spill Buckets		-1		
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(V)No	OperatorNotified	(Ves	\bigcap_{i}
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	\times
	Fill Ports	0		0.3	\mathcal{O}°
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	No	OperatorNotified	Cres	Olo
	ping/STP Sur	nps	.1	0	
Are Sumps Clean and free from water, debris, product etc?	OYes .	(<u>v</u>)/o	OperatorNotified	(Ves	Olo.
Under Dispe	enser Contain	ments (UDC)			0.0
Are UDCs clean and free from water, debris, product etc?	Yes	(No	Operator Notified	(Ves	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF A	ACCORDING CERTIFIED	TO EXISTING DITLES	AND REQU	ILATIONS
Operator on Duty Name	Signature			Date	
317-645-0215 tanks	ksdata@gmail.com			www.tanksdata.com	
Mark	and Simult.	J.1.1		www.tanks	data.com

tanksuata@yman.com.