

30 DAYS WALK THROUGH INSPECTION

Tanks Data		Contact Number
UST Facility I.D. (RID) #	16239	Contact email
Facility Name	Phillips 66	Date of Inspection
Address	613 Pine Lake Ave, La Bate	10/14/24
Operator on Duty Name	IN 46350	Name of the Person Conducting Inspection
		AKSHIT
Operator Training current	☐ Yes ☐ No	Operator Notified
Is Registration current with correct owner, operator etc.	☐ Yes ☐ No	Operator Notified
Release Detection Method	☒ ATG ☐ DIM	Operator Notified
Make and Model	LR TLS 350	Operator Notified
Does it have paper?	☒ Yes ☐ No	Operator Notified
Is it in Alarm mode?	☒ Yes ☐ No	Operator Notified
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No	Operator Notified
Necessary Monthly Printout Taken	☒ Yes ☐ No	Operator Notified
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Notified
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No	Operator Notified
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes ☐ No	Operator Notified
Are Sumps Clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Notified
Under Dispenser Containments (UDC)	☒ Yes ☐ No	Operator Notified
Are UDCs clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Notified

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name _____ Signature _____ Date _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com 20720516