Tanks Data		30 DAYS V	VALK THROUG	HINSPEC	CTION	
UST Facility I.D.((FID) # 16239	Contact N	Contact Number				
Facility Name Olioils	Contact er	Contact email				
Address 613 Pine Lake ANG 46350	Date of In	Date of Inspection $06-13-702$				
Operator on Duty Name		Name of the Person Conducting Inspection Guerbreet				
	perator Train	ning			<u> </u>	
Operator Training current	Yes	ONo	OperatorNotified	Yes	ON <sub>0</sub>	
	ation/Notifica	/ \	O A Notified	0	Oto	
Is Registration current with correct owner, operator etc.	Yes	ONo.	OperatorNotified	Vres	O40	
	Release Detect	CIM	()SIR	OIC	Other	
Release Detection Method	STATE	O				
Make and Model V K 125 - 2	Yes	No	OperatorNotified	Yes	Olo	
Does it have paper?	Yes	No	OperatorNotified	Yes	Olo	
Is it in Alarm mode?	<b>X</b> .	No	OperatorNotified	Yes	No	
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No	
Necessary Monthly Printout Taken	(V) Yes		Орегино			
	Spill Buckets	Phi	OperatorNotified	@Tes	Olo	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	ZNO No	OperatorNotified	Yes	No	
Are the Spill Bucket in good condition and free of damage/cracks	res	ONO	Operatornomica	O		
	Fill Ports Yes	No	OperatorNotified	Tes	Olo	
Is Fill pipe cap tight and fill pipe free from any obstruction?	ping/STP Sun					
	Yes	(9)No	OperatorNotified	Wes .	Olo	
Are Sumps Clean and free from water, debris, product etc?  Under Disper				7		
가 보고 있다면 나는 사람들은 사람들이 들어지는 것을 하는 것이 하는 것이 없는 것이 없습니 없는 것이 없습니 없는 것이 없습니 없는 것이 없습니 없습니 없습니 없습니 없습니 없습니 없습니 없습니 없었다면 없었다면 없었다면 없었다면 없었다면 없었다면 없었다면 없었다면	Yes	(No	OperatorNotified	Gres	Olo	
Are UDCs clean and free from water, debris, product etc?	OSSED OFF A	CCORDING T	O FXISTING RULES	AND REQUL	ATIONS	
Are UDCs clean and free from water, debris, product etc.  NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPORTED FOLLOWING PROPER PROCESSION.	CEDUE BY A	12.	ONTRACTOR.	Data Sh.	-13-202	
erator on Duty Name		Signature				
tonkede	ata@gmail.com	n Jurps		www.tanksda		
317-645-0215					20220516	