Tanks Data		30 DAYS WALK THROUGH INSPECTION			
UST Facility I.D.((FID) # 16239	Contact N	Contact Number			
Facility Name Phyllips 66	Contact er	Contact email			
Address (139mil ste ANC	Date of In	Date of Inspection $08-11-703$			
Operator on Duty Name		Name of the Person Conducting Inspection Conducting Inspection			
0	perator Train	ing	/		
Operator Training current	Yes	ONo	OperatorNotified	Yes	ON ₀
Is Registration current with correct owner, operator etc.	tion/Notification/Yes elease Detecti	ONO	OperatorNotified	Ores	Oto
Release Detection Method	ATG	CIM	SIR	OIC	Other
Make and Model TIRT 5-3	50				
Does it have paper?	Yes	No	OperatorNotified	Yes	Oto
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Olo
Necessary Monthly Printout Taken	Yes	ON _o	OperatorNotified	Yes	Olo
	Spill Buckets				
re Spill Buckets Clean and free from water, debris, product etc?	Ves	(DNo	OperatorNotified	es	Olo
re the Spill Bucket in good condition and free of damage/cracks	Yes Fill Ports	ONo	OperatorNotified	Oes	Oıo
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes ng/STP Sum	ONO	OperatorNotified	Oes	Oio
The second secon	Yes	No	OperatorNotified	Q Yes	No
Are Sumps Clean and free from water, debris, product etc? Under Dispens		No.	Operatornomica		O
	Yes	(ODC)	OperatorNotified	OYes	Ovo
Are UDCs clean and free from water, debris, product etc?			님이는 그는 항상이 되었다면 살아가는 사람들이 되었다.	4	II ATIONS
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOS FOLLOWING PROPER PROCE	EDUE BY A C	CORDING T CERTIFIED C	ONTRACTOR.	AND REQU	LAHIONS
tor on Duty Name		Signature		Date	
	@gmail.com		2	www.tanks	data.com