Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)# 1739	Contact No	Contact Number			
Facility Name Phil like 6	Contact email				
Address (13/2/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1/1	Date of Inspection 09 - 19 - 2025				
Operator on Duty Name	Name of the Person Conducting Inspection Conducting Inspection				
	perator Train	construence de German es consideran en construence	auguer		
Operator Training current	Yes	ONo	OperatorNotified	Yes	Ovo
[마일::) 전에 살아진 생각을 살아가는 나이 보다면 하는데 살아 보면 하는데 다른데 나이를 가면 하는데, 그런데 ()(ation/Notifica	tion Form		0	
Is Registration current with correct owner, operator etc.	Yes	No	OperatorNotified	Ves	Olo
	elease Detect	A	Ostra	000	Own
Release Detection Method	ATG	CEIM	SIR	Oic	Other
Make and Model / Q ()	250		OperatorNotified	Ovan	0
Does it have paper?	Yes	QNo.		Yes	X
Is it in Alarm mode?	Yes	QNo.	OperatorNotified	Xes	No.
Interstitial Monitoring Sensor Status Normal	Yes	ONO.	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	€Yes	ONO	OperatorNotified	Yes	ONO
	Spill Bucket	S			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	No	OperatorNotified	es	Oio
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ONO	OperatorNotified	Oes	Olo
	Fill Ports				
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	ONO.	OperatorNotified	Oes	Olo
The contract of the contract o	iping/STP Su	mps		0	
Are Sumps Clean and free from water, debris, product eto?	Yes	No	OperatorNotified	res	Oxo
The state of the s		nments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified		Cho
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS	POSSED OFF OCEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	JLATIONS
Operator on Duty Name		Signature		Date	
사용하다 사람들은 그는 사람이 아이를 하고 한 가장 되었다. 그리는 이 아이들은 아이들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람들은 사람	sdata@gmail.	com		www.tank	sdata.com
					202205