Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)# 16239	Contact Number				
Facility Name O Philleps	Contact en	Contact email			
Address 6/3 Vine habe Alice 46 350	Date of Ins	Date of Inspection $0-10-7075$			
Operator on Duty Name		Name of the Person Conducting Inspection Grands Conducting Inspection			
0]	perator Train				
Operator Training current	Yes	ONo	OperatorNotified	Yes	ONo
Is Registration current with correct owner, operator etc.	tion/Notificat	Ovo	OperatorNotified	Ores	Oio
	elease Detecti			010	0
Release Detection Method	4 PATE	CIM	SIR	Oic	Other
Make and Model (() () () ()	Yes	No	OperatorNotified	Yes	Oio
Is it in Alarm mode?	Yes	No	OperatorNotified	Yes	No
Interstitial Monitoring Sensor Status Normal	tes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	res	Oio
	Spill Buckets				
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	@No	OperatorNotified	es	Oio
Are the Spill Bucket in good condition and free of damage/cracks	O'res	ONO	OperatorNotified	es	Olo
	Fill Ports	<u> </u>			
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes .	ON0	OperatorNotified	Jes	Olo
Are Sumps Clean and free from water, debris, product etc?	ng/STP Sum	No	OperatorNotified	0	
Under Dispens	ser Containn		물에게 된 경기에 깨끗을 잃었다면 하는 때 전에 가게 지어갔다. 나는 그 모든 나를	Vres	Cho
Are UDCs clean and free from water, debris, product etc?	Yes	No	OperatorNotified	Yes	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOS FOLLOWING PROPER PROCE	SSED OFF ACEDUE BY A C	CCORDING	TO EXISTING RULES		ILATIONS
rator on Duty Name		Signature		Date	
317-645-0215 tanksdat	a@gmail.con	1		www.tanks	data.com