

 EZY CHEK SYSTEMS LEAK DETECTOR TEST AN ENVIRONMENTAL COMPLIANCE COMPANY 316 W. Indiana Ave. Chesterton, IN 46304 REVISION 8/21/2019				DATE AND TIME		1-30-23 - 1:00 PM		
				WEATHER		20 Snow		
				COLLECT/INVOICE		Collected		
				CLIENT EMAIL		-		
				Testing Company Information				
Test Location Information				Certifications		Name		Midwest Tank Testing
PC # and WO #				Estabrooks: 82-1906		Address		316 W. Indiana Ave.
Name and FID #		Phillips 66 - FID 15454		ICC: 10221928		City/State/Zip		Chesterton, IN 46304
Address		4005 Western Ave.		Indiana: UC 110386		Phone		800-975-1436
City/State/Zip		South Bend, IN 46619		CP/STI: 16655		Technician Information		
Contact				UC111023		Name		Chris Zell
Phone						Email		support@midwesttanktesting.com
TYPE OF LEAK DETECTOR - (LD) or (ELD)								
PUMP #		PRODUCT		MODEL		SERIAL # (If Legible)		
1		Regular		FePetro/FePetro		N/A		
2		Premium		FePetro/FePetro		N/A		
3								
4								
5								
6								
7								
8								
LEAK DETECTOR TEST								
PUMP #		Product Type	Metering Pressure	Functional Element Holding PSI	Resiliency	Test Leak Rate ML/MIN	Opening Time	Results
1		Regular	26	26	150	189ml	2	Pass
2		Premium	26	26	130	189ml	2	Pass
3						189ml		
4						189ml		
5						189ml		
6						189ml		
7						189ml		
8						189 ml		
COMMENTS/RECOMMENDATIONS:								



AN ENVIRONMENTAL COMPLIANCE COMPANY

316 W. Indiana Ave.
Chesterton, IN 46304

EZY CHEK SYSTEMS

PRODUCT LINE TEST

DATE AND TIME

1-30-23 - 1:00 PM

Test Location Information

PC # and WO #	
Name and FID #	Phillips 66 - FID 15454
Address	4005 Western Ave.
City/State/Zip	South Bend, IN 46619
Contact	
Phone	

Testing Company Information

Name	Midwest Tank Testing
Address	316 W. Indiana Ave.
City/State/Zip	Chesterton, IN 46304
Phone	800-975-1436

Technician Information

Name	Chris Zell
Email	support@midwesttanktesting.com
Applied Pressure	1-1/2 Times Working Pressure, Min 50 PSI

PRODUCT LINE TEST - DATA (LT)

#1	Product Type:		Regular		
TIME	DATA	-/+	GPL	RES	GPH
1:30	90	0	0.0037	0.0000	0.0000
1:45	90	0	0.0037	0.0000	0.0000
2:00	90	0	0.0037	0.0000	0.0000
2:15	90	0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
FINAL RESULT:			Pass		

#2	Product Type:		Premium		
TIME	DATA	-/+	GPL	RES	GPH
1:30	90	0	0.0037	0.0000	0.0000
1:45	90	0	0.0037	0.0000	0.0000
2:00	90	0	0.0037	0.0000	0.0000
2:15	90	0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
FINAL RESULT:			Pass		

#3	Product Type:				
TIME	DATA	-/+	GPL	RES	GPH
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
FINAL RESULT:					

#4	Product Type:				
TIME	DATA	-/+	GPL	RES	GPH
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
FINAL RESULT:					

#5	Product Type:				
TIME	DATA	-/+	GPL	RES	GPH
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
FINAL RESULT:					

#6	Product Type:				
TIME	DATA	-/+	GPL	RES	GPH
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
		0	0.0037	0.0000	0.0000
FINAL RESULT:					

COMMENTS/RECOMMENDATIONS: Prem shut off valve and check valve plug needs repaired.