Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID)# 5394	Contact Number				
Facility Name Marachon	Contact email				
Address 270/ Project 4/5/2	Date of Inspection $06-76-7075$				
Operator on Duty Name	Name of the Person Conducting Inspection Graphreet				
Operator Training					
Operator Training current	Oyes	ONo	OperatorNotified	Yes	ON <sub>0</sub>
Is Registration current with correct owner, operator etc.	on/Notificati	on Form No	OperatorNotified	Ores	O <sub>10</sub>
# 하면 있게 하면 하는 경험 전에 가는 사이를 가게 되었다. 그런 역상에 있는 것은 사이를 하는 것이 되었다고 있다면 하는 것이다면 하는 것이다. 그런 것이다면 하는 것이다면 하는데	ease Detection	on OZIM	OSIR	Oic	Other
Make and Model TS 750TAN  Does it have paper?	K Sent OYes	S resto No	OperatorNotified	OYes	O10
Is it in Alarm mode?	Yes	No	OperatorNotified	OYes	010
Interstitial Monitoring Sensor Status Normal	Yes	X <sub>N</sub> ₀	OperatorNotified	O'res	Oıo
Necessary Monthly Printout Taken	Yes	O <sub>No</sub>	OperatorNotified	Ores	O <sub>10</sub>
Spill Buckets					
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	<b>€</b> No	OperatorNotified	es	$\mathcal{L}^{\circ}$
Are the Spill Bucket in good condition and free of damage/cracks	Wes Fill Ports	$O_{N^{\circ}}$	OperatorNotified	Oes	$O_{i0}$
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	010
	ng/STP Sum	ips		8	<u> </u>
Are Sumps Clean and free from water, debris, product etc?	OYes .	(O)0	OperatorNotified	Ores	$\bigcirc$
Under Dispens	$\overline{}$			<b>~</b>	<u> </u>
	Yes	€No	OperatorNotified		$\bigcirc$
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSSED OFF ACCORDING TO EXISTING RULES AND REQULATIONS FOLLOWING PROPER PROCEDUE BY A CERTIFIED CONTRACTOR.					
Operator on Duty Name		Signature		Date 06 -	76-2025
317-645-0215 tanksda	ta@gmail.co	m yurbrox	2	www.tanksda	ata.com 20220516