

000
Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #	16738	Contact Number	
Facility Name	MIRATHON	Contact email	
Address	13060 Jefferson Blvd, Mishawaka	Date of Inspection	11/28/24
Operator on Duty Name	IN 46545	Name of the Person Conducting Inspection	AKSHIT

Operator Training current	Operator Training	Registration/Notification Form	Release Detection
Is Registration current with correct owner, operator etc.	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Release Detection Method	☒ ATG ☐ DIM ☐ SIR		☐ IC ☐ Other
Make and Model	VR 715 450 Plus		
Does it have paper?	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Is it in Alarm mode?	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Necessary Monthly Printout Taken	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No

Spill Buckets	Fill Ports	Operator Notified	Operator Notified
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?	Pipeline/STP Sumps	Operator Notified	Operator Notified
☒ Yes ☐ No	☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?	Under Dispenser Containments (UDC)	Operator Notified	Operator Notified
☒ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No	☐ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name _____ Signature _____ Date _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com