

Tanks Data

30 DAYS WALK THROUGH INSPECTION

UST Facility I.D. (FID) #	16738	Contact Number	
Facility Name	Merethon	Contact email	
Address	13060 Jefferson Blvd,	Date of Inspection	04-27-25
Operator on Duty Name	Miguel Alvarez Jr - 46545	Name of the Person Conducting Inspection	Miguel Alvarez Jr

Registration/Notification Form		Operator Training	
Is Registration current with correct owner, operator etc.	☐ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Release Detection current with correct owner, operator etc.	☐ Yes ☐ No	Operator Training current	☐ Yes ☐ No

Release Detection		Operator Training	
Release Detection Method	☒ ATG ☐ TIM ☐ SIR ☐ IC ☐ Other	Operator Training current	☐ Yes ☐ No
Make and Model	VR-TL5450 Plus	Operator Training current	☐ Yes ☐ No
Does it have paper?	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Is it in Alarm mode?	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Necessary Monthly Printout Taken	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No

Spill Buckets		Operator Training	
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Are Sumps Clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No
Are UDCs clean and free from water, debris, product etc?	☒ Yes ☐ No	Operator Training current	☐ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name: _____ Signature: _____ Date: _____

317-645-0215 tanksdata@gmail.com www.tanksdata.com 20220516