

Tanks Data		30 DAYS WALK THROUGH INSPECTION	
UST Facility I.D. (FID) #	5476	Contact Number	
Facility Name	Marathon	Contact email	
Address	335 W McKinley Ave Mishawaka	Date of Inspection	4/28/23
Operator on Duty Name	46545	Name of the Person Conducting Inspection	Josh Rider
Operator Training			
Operator Training current	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Registration/Notification Form			
Is Registration current with correct owner, operator etc.	☐ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Release Detection			
Release Detection Method	☒ ATG ☒ EIM ☐ BIR ☐ IC ☐ Other		
Make and Model	VR TLS-350		
Does it have paper?	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Is it in Alarm mode?	☐ Yes ☒ No	Operator Notified	☐ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Necessary Monthly Printout Taken	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Spill Buckets			
Are Spill Buckets Clean and free from water, debris, product etc?	☐ Yes ☒ No	Operator Notified	☒ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Fill Ports			
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes ☐ No	Operator Notified	☐ Yes ☐ No
Piping/STP Sumps			
Are Sumps Clean and free from water, debris, product etc?	☐ Yes ☒ No	Operator Notified	☒ Yes ☐ No
Under Dispenser Containments (UDC)			
Are UDCs clean and free from water, debris, product etc?	☐ Yes ☒ No	Operator Notified	☒ Yes ☐ No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.			
Operator on Duty Name	Signature	Date	
317-645-0215	tanksdata@gmail.com	www.tanksdata.com	

MARATHON 3107
335 W.MCKINLEY
MIS #44464 IN 46545

APR 28, 2023 11:07 AM

OSLO TEST RESULTS

APR 28, 2023 11:07 AM

T 1:REGULAR
PROBE SERIAL NUM 812581
0.2 GAL/HR TEST
PER: APR 28, 2023 PASS

T 2:PREMIUM
PROBE SERIAL NUM 812766
0.2 GAL/HR TEST
PER: APR 28, 2023 PASS

* * * * * END * * * * *

MARATHON 3107
335 W.MCKINLEY
MIS #44464 IN 46545

APR 28, 2023 11:07 AM

LIQUID STATUS

APR 28, 2023 11:07 AM

L 2:DEAD SLOT
SENSOR NORMAL

L 3:DEAD SLOT
SENSOR NORMAL

L 4:INT PREM
SENSOR NORMAL

* * * * * END * * * * *

MARATHON 3107
335 W.MCKINLEY
MIS #44464 IN 46545

APR 28, 2023 11:07 AM

LEAK TEST REPORT

T 1:REGULAR
PROBE SERIAL NUM 812581

TEST STARTING TIME:
OCT 19, 2017 11:48 AM

HEIGHT = 53.8 INCHES
WATER = 0.0 INCHES
TEMP = 55.1 F

TEST LENGTH = 2.0 HRS
SIFT VOLUME = 8412.3 GAL
PERCENT VOLUME = 55.2

LEAK TEST RESULTS
RATE = -143.83 GAL/HR
THRS = -0.13 GAL/HR
0.20 GAL/HR TEST FAIL

* * * * * END * * * * *

MARATHON 3107
335 W.MCKINLEY
MIS #44464 IN 46545

APR 28, 2023 11:07 AM

LEAK TEST REPORT

T 2:PREMIUM
PROBE SERIAL NUM 812766

TEST STARTING TIME:
OCT 19, 2017 11:48 AM

HEIGHT = 22.7 INCHES
WATER = 0.8 INCHES
TEMP = 79.8 F