Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 5476	Contact Number				
Facility Name Marathon	Contact email				
Address 335 W McKinley Ave Mishawaka	Date of Inspection $3/21/23$				
Operator on Duty Name 46545	Name of the Person Conducting Inspection Josh		lider		
O	perator Train				_
Operator Training current	Yes	No	OperatorNotified	O'res	O _{No}
Registra	tion/Notifica	tion Form		_	
Is Registration current with correct owner, operator etc.	Yes	Oyo	OperatorNotified	Ves	Oto
	elease Detecti		_	_	_
Release Detection Method	√ ATG	CIM	SIR	Orc	Other
Make and Model	VR	TLS-3	350		
Does it have paper?	Yes	O_{No}	OperatorNotified	Yes	O40
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	O'res	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	Oyo
Necessary Monthly Printout Taken	Yes	No	OperatorNotified	() res	O ₁₀
	Spill Bucket	,			
Are Spill Buckets Clean and free from water, debris, product etc?	()res	(V)vo	OperatorNotified	(V)es	No
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	O ₁₀
The second section of the section of th	Fill Ports				_
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O ₁ o	OperatorNotified	Oes	Oto
Pij	oing/STP Sur			~	
Are Sumps Clean and free from water, debris, product etc?	Yes	⊘ 10	OperatorNotified	(Vres	Olo
Under Dispe	nser Contain	ments (UDC)		-/	_
Are UDCs clean and free from water, debris, product etc?	Yes	Ø√o	OperatorNotified	(V) res	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO				AND REQUI	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksd	tanksdata@gmail.com			www.tanksdata.com	