Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # 5476	Contact Number				
Facility Name Marathon	Contact email				
Address 335 W McKinley Ave Mishawaka	Date of Inspection 1/19/23		1/19/23		
Operator on Duty Name 46545	Name of the Person Conducting Inspection		Josh Ride	Υ	
Op	erator Train	ing			
Operator Training current	Oyes	ONo	OperatorNotified	Yes	ONO
	ion/Notificat	tion Form		0	_
Is Registration current with correct owner, operator etc.	OYes .	Oyo	OperatorNotified	Ves	Olo
	lease Detecti	_			_
Release Detection Method	√ ATG	C IM	SIR	OIC	Other
Make and Model	VR .	TLS-350)	_	
Does it have paper?	Yes	O_{No}	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	(V)No	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	(V)Yes	\bigcirc No	OperatorNotified	Yes	No
	Spill Buckets	s		0	
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(No	OperatorNotified	(T)es	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)Yes	No	OperatorNotified	es	No
	Fill Ports	0	.,,:		0.0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(V)Yes	No	OperatorNotified	Cres	ONO.
Pij	ping/STP Sur	mps			0.0
Are Sumps Clean and free from water, debris, product etc?	Yes	$\sqrt{\lambda}$	OperatorNotified	(V)/es	ONO.
Under Dispe	nser Contain	ments (UDC)		0.0
Are UDCs clean and free from water, debris, product etc?	Yes	\bigcirc No	OperatorNotified	Yes	Oko
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF CEDUE BY A	ACCORDING 4 CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksdata@gmail.com				www.tanksdata.com	
					2022