Tanks Data	30 DAYS WALK THROUGH INSPECTION				
ST Facility I.D.( (FID) # 5476	Contact Number				
acility Name Marathon	Contact email				
ddress 335 W McKinley Ave Mishawaka	Date of Inspection $\frac{2}{21}/\frac{23}{23}$				
Operator on Duty Name 46545	Name of the Person Conducting Inspection		Josh Rider		
0	perator Train				
Operator Training current	Oyes	ON <sub>0</sub>	OperatorNotified	(Yes	ONO
Registr	ation/Notifica	tion Form		_	
Is Registration current with correct owner, operator etc.	Yes	$\bigcirc$ Vo	OperatorNotified	O'es	Olo
	Release Detect				_
Release Detection Method	ATG	<b>CIM</b>	SIR	OIC	Other
Make and Model	VR	TL5-35	10	·	
Does it have paper?	Yes	$O_{N^0}$	OperatorNotified	Yes	Olo
Is it in Alarm mode?	Yes	(V)Vo	OperatorNotified	Yes	Olo
Interstitial Monitoring Sensor Status Normal	Yes	No	OperatorNotified	Yes	No
Necessary Monthly Printout Taken	Yes	ŎNo	OperatorNotified	Yes	No
	Spill Bucket	is			0
Are Spill Buckets Clean and free from water, debris, product etc?		(No	OperatorNotified	(Vies	Olo
Are the Spill Bucket in good condition and free of damage/cracks	(V)res	No	OperatorNotified	Ges	No
	Fill Ports	0		0	0.
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	Ovo	OperatorNotified	Oes	Olo
P	iping/STP Su	mps		_	
Are Sumps Clean and free from water, debris, product etc?	Yes	<b>⊘</b> /o	OperatorNotified	(V)res	No
Under Disp	enser Contain	nments (UDC)		_	0
Are UDCs clean and free from water, debris, product etc?	OYes	(No	OperatorNotified	(Ves	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DIS FOLLOWING PROPER PR	POSSED OFF OCEDUE BY A	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tank	sdata@gmail.com			www.tanksdata.com	