

30 DAYS WALK THROUGH INSPECTION

Tanks Data	
UST Facility I.D. (FID) #	5476
Facility Name	MARA THERM
Address	335 W McKinley Ave, Milwaukee, WI 53245
Operator on Duty Name	AKSHAT
Contact Number	
Contact email	
Date of Inspection	12/22/24
Name of the Person Conducting Inspection	AKSHAT
Operator Training	
Operator Training current	☐ Yes ☐ No
Registration/Notification Form	☐ Yes ☐ No
Release Detection	☐ Yes ☐ No
Release Detection Method	ATG ☒ TIM ☐ BIR ☐ IC ☐ Other
Make and Model	VR TIS 350
Does it have paper?	☒ Yes ☐ No
Is it in Alarm mode?	☒ Yes ☐ No
Interstitial Monitoring Sensor Status Normal	☒ Yes ☐ No
Necessary Monthly Printout Taken	☒ Yes ☐ No
Spill Buckets	
Are Spill Buckets Clean and free from water, debris, product etc?	☒ Yes ☐ No
Are the Spill Bucket in good condition and free of damage/cracks	☒ Yes ☐ No
Is Fill pipe cap tight and fill pipe free from any obstruction?	☒ Yes ☐ No
Pipeline/STP Sumps	☒ Yes ☐ No
Are Sumps Clean and free from water, debris, product etc?	☒ Yes ☐ No
Under Dispenser Containments (UDC)	☒ Yes ☐ No
Are UDCs clean and free from water, debris, product etc?	☒ Yes ☐ No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.	
Operator on Duty Name	Signature
317-645-0215	Date
tanksdata@gmail.com	www.tanksdata.com