

30 DAYS WALK THROUGH INSPECTION

000
Tanks Data

UST Facility I.D. (FID) # 5476

Contact Number

Facility Name MARRHAN

Contact email

Address 335 C. McKinley Ave Milwaukee

Date of Inspection

06/02/24

Operator on Duty Name

IN 4645

Name of the Person Conducting Inspection

AKSHIT SAMPARAN

Operator Training current

Operator Training
☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is Registration current with correct owner, operator etc.

Registration/Notification Form
☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Release Detection Method

Release Detection
☒ MTG ☐ TIM

☐ SIR

☐ IC

☐ Other

Make and Model

VR 725352

Does it have paper?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is it in Alarm mode?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Interstitial Monitoring Sensor Status Normal

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Necessary Monthly Printout Taken

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Spill Buckets

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are Spill Buckets Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are the Spill Bucket in good condition and free of damage/cracks

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Is Fill pipe cap tight and fill pipe free from any obstruction?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Pipeline/STP Sumps

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are Sumps Clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

Are UDCs clean and free from water, debris, product etc?

☒ Yes ☐ No

Operator Notified

☒ Yes ☐ No

NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPOSED OFF ACCORDING TO EXISTING RULES AND REGULATIONS FOLLOWING PROPER PROCEDURE BY A CERTIFIED CONTRACTOR.

Operator on Duty Name

Signature

Date

317-645-0215

tankdata@gmail.com

www.tankdata.com

20220516