Tanks Data		30 DAYS W	ALK THROUGH	INSPE	CTION
UST Facility I.D.((FID)# 59776	Contact Number				
Facility Name May-Bhall	Contact email				
Address 33 5 m My birley All 46549					
Operator on Duty Name	Name of the Person Conducting Inspection Conducting Inspection				
Op	erator Train		1		
Operator Training current	Oyes	(No	OperatorNotified	Yes	(No
Registrat	tion/Notifica	tion Form		~	
Is Registration current with correct owner, operator etc.	Yes	Ovo	OperatorNotified	Ores	Oio
있다. 전 하는 경영 전 경영	lease Detect	ion			
Release Detection Method	MTG	Ø CIM	O SIR	Oic	Other
Make and Model URT25 - 39	56				
Does it have paper?	Yes	O _{No}	OperatorNotified	Yes	\bigcirc
Is it in Alarm mode?	Yes	O _N o	OperatorNotified	Ores	O10
Interstitial Monitoring Sensor Status Normal	Yes	ONo.	OperatorNotified	()res	ONO
Necessary Monthly Printout Taken	Yes	Ŏ _N o	OperatorNotified	Tes	Ovo
	Spill Bucket	s			
Are Spill Buckets Clean and free from water, debris, product etc?	Ores	9No	OperatorNotified	(C)es	O _V o
Are the Spill Bucket in good condition and free of damage/cracks	Yes	ON₀	OperatorNotified	es	ONO.
	Fill Ports	_			_
Is Fill pipe cap tight and fill pipe free from any obstruction?	Yes	O ₁₀	OperatorNotified	Oes	Oio
Pip	ing/STP Sur	nps		~	
Are Sumps Clean and free from water, debris, product etc?	Yes	(P)No	OperatorNotified	Ores	ONO.
Under Disper	nser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	ØN ₀	OperatorNotified	Ores	Olo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PROC				AND REQU	LATIONS
perator on Duty Name		Signature		Date 7	2-10-707
	ata@gmail.com			www.tanksdata.com	
		, 0			202205