Tranks Data		30 DAYS W	ALK THROUGE	I INSPE	CTION
UST Facility I.D.((FID)# 5476	Contact Number				
Facility Name Mounthyon	Contact email				
Address 37 5 WM binduga 4054	Date of Inspection $08-13-2025$				
Operator on Duty Name	Name of the Person Conducting Inspection Conducting Inspection				
0	perator Train				
Operator Training current	Yes	(No	OperatorNotified	Yes	(No
[대일 역장 [대일 : [대일 : [대일 : [대] : [대일 : [대] : [대일 : [대] :	tion/Notification/Yes	tion Form	OperatorNotified	Ores	010
${f R}$	elease Detect	ion			<u> </u>
Release Detection Method	(E)ATG	& CIM	SIR	Oic	Other
Make and Model VR 165-25	0		OperatorNotified	Over	\bigcirc To
Does it have paper?	Yes	Q^{N_0}		X	X
Is it in Alarm mode?	XYes ?	QNo	OperatorNotified	Yes	7.0
Interstitial Monitoring Sensor Status Normal	(C) Yes	O _{No}	OperatorNotified	Yes	No.
Necessary Monthly Printout Taken	Yes	ONO	OperatorNotified	Ores	O _{No}
	Spill Bucket	3		0	0-
Are Spill Buckets Clean and free from water, debris, product etc?		ØN ₀	OperatorNotified	2 es	Υ."
Are the Spill Bucket in good condition and free of damage/cracks		O _N o	OperatorNotified	Oes	O**
	Fill Ports Yes	(No	OperatorNotified	Tes	Oko
Is Fill pipe cap tight and fill pipe free from any obstruction?	ping/STP Sur				
Are Sumps Clean and free from water, debris, product etc?	Yes	ONo	OperatorNotified	Pres	No
Under Dispe	nser Contain	ments (UDC)			
Are UDCs clean and free from water, debris, product etc?	Yes	ØN₀	OperatorNotified		Ovo
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISP FOLLOWING PROPER PRO	OSSED OFF	ACCORDING	TO EXISTING RULES. CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
그는 지나는 사람들이 얼마나 되었다면 하는데 얼마를 하는데 되었다면 하는데 되었다면 하는데	anksdata@gmail.com			www.tanksdata.com	
					202203