	•		P 1T 1/02/22 3:36 PM 1U 19379 GPM # 5637 U 499 US HWY 20
Tanks Data 30 DAYS WALK THROUGH INSPECTION		DUTH BEND, IN 46628 p '4-287-0837	
UST Facility I.D.((FID) # 15670	Contact Number		T LESSURE LINE LEAK REPORTS
Facility Name BP	Contact email		JU ISSED TESTS HISTORY
Address 26499 US-20 South Bend 46628	Date of Inspection 9/2/22		VI 1: UNLEAD
Operator on Duty Name	Name of the Person Conducting Inspection Josh Rid	er	i.P
	Operator Training		T I
Operator Training current	Yes No OperatorNotified	Yes No	N.
Regi	tration/Notification Form		/G1 2: DIESEL
Is Registration current with correct owner, operator etc.	Yes No OperatorNotified C	Yes Olo	iF
Release Detection Method	(VATG CIM SIR C	IC Other	in the second se
Make and Model	VR TLS-450 Plus)(1 3: PREMIUM
Does it have paper?	Yes No OperatorNotified	Yes No	15
Is it in Alarm mode?	Yes No OperatorNotified	Yes No	H
Interstitial Monitoring Sensor Status Normal	Yes No OperatorNotified	Yes No	15
Necessary Monthly Printout Taken	es No OperatorNotified	res No	1
	Spill Buckets tc? Ves No OperatorNotified (Tra Ota	la l
Are Spill Buckets Clean and free from water, debris, product		$\prec :$ $\prec :$	
Are the Spill Bucket in good condition and free of damage/cra	Fill Ports		ii v
Is Fill pipe cap tight and fill pipe free from any obstruction	Yes No OperatorNotified (Jes Vio	X
Are Sumps Clean and free from water, debris, product etc?	Yes No OperatorNotified	Yes No	1
Linder	ispenser Containments (UDC)		
Are UDCs clean and free from water, debris, product etc?	Yes No OperatorNotified ()res (No	
NOTE AND LOUID DEDDIE OF WASTE MIST RE	DISPOSSED OFF ACCORDING TO EXISTING RULES AN PROCEDUE BY A CERTIFIED CONTRACTOR.	D REQULATIONS)//02/22 3:36 PM
		Date	19379 GPM # 5637
Operator on Duty Name		ww.tanksdata.com	i499 US HWY 20
317-645-0215	anksdata@gmail.com		20220516 V4-287-0837
			NK LEAK TEST HISTORY - NSSED TEST RESULTS 1: UNLEAD PORT TYPE = LAST GROSS NTE/TIME = 09/02/22 4:16 THOD = SLD Gross Test
			VOLUME = 1780 VOLUME = 14.8