Tanks Data	30 DAYS WALK THROUGH INSPECTION				
UST Facility I.D.((FID) # \\ \15670	Contact Number				
acility Name BP	Contact email				
Address 26499 US-20 South Bend 46628	Date of Inspection 2/26/24				
Operator on Duty Name	Name of the Person Conducting Inspection Josh Ri			der	
Op	erator Train	ning		_	_
Operator Training current	Yes	ON ₀	OperatorNotified	OYes .	\bigcirc_{N^0}
Registrat	tion/Notifica			0	
Is Registration current with correct owner, operator etc.	Yes	. Oy₀	OperatorNotified	Ves	\bigcirc
	lease Detect	^	O	0	<u> </u>
Release Detection Method	⊘ ATG	CIM	OSIR	Oic	Other
Make and Model	VR	TLS-4		_	
Does it have paper?	Yes	O _N o	OperatorNotified	Yes	\bigcirc 10
Is it in Alarm mode?	Yes	$\bigcirc_{N^{\circ}}$	OperatorNotified	(Ves	\bigcirc Io
Interstitial Monitoring Sensor Status Normal	Yes	O _V o	OperatorNotified	O'res	Ovo
Necessary Monthly Printout Taken	Yes	\bigcirc No	OperatorNotified	Yes	No
	Spill Bucke	ts			
Are Spill Buckets Clean and free from water, debris, product etc?	Yes	(V)Vo	OperatorNotified	(Ves	Olo
Are the Spill Bucket in good condition and free of damage/cracks	Yes	No .	OperatorNotified	Ves	\sim
	Fill Ports	missin	9 lid	v	0
Is Fill pipe cap tight and fill pipe free from any obstruction?	(Ves	O\o	OperatorNotified	(Tes	Olo
Pip	ping/STP Su	mps		_	
Are Sumps Clean and free from water, debris, product etc?	Oyes	⊘ √o	OperatorNotified	Ves	No
Under Dispe	nser Contai	nments (UDC)			0
Are UDCs clean and free from water, debris, product etc?	Yes	Olo	OperatorNotified	O'es	No
NOTE: ALL LIQUID/DEBRIS OR WASTE MUST BE DISPO FOLLOWING PROPER PRO	OSSED OFF CEDUE BY	ACCORDING A CERTIFIED	TO EXISTING RULES CONTRACTOR.	AND REQU	LATIONS
Operator on Duty Name		Signature		Date	
317-645-0215 tanksdata@gmail.com				www.tankso	lata com