

03/24 4:07 PM

9379 GPM # 5637
199 US HWY 20
JTH BEND, IN 46628
4-287-0837

ESSURE LINE LEAK REPORTS
SSED TESTS HISTORY

1: UNLEAD

2: DIESEL

3: PREMIUM

03/24 4:07 PM

9379 GPM # 5637
499 US HWY 20
UTH BEND, IN 46628
4-287-0837

NK LEAK TEST HISTORY -
SSED TEST RESULTS

1: UNLEAD

PORT TYPE = LAST GROSS
TE/TIME = 06/03/24 1:28
THOD = SLD Gross Test
G. VOLUME = 887
VOLUME = 7.4

PORT TYPE = LAST PERIODIC
TE/TIME = 06/03/24 2:02
THOD = CSLD Periodic Test
URS = 20
G. VOLUME = 6686
VOLUME = 55.6

PORT TYPE = FULLEST PERIODIC
TE/TIME = 06/01/24 3:40
THOD = CSLD Periodic Test
URS = 23
G. VOLUME = 6743
VOLUME = 56.0

PORT TYPE = FULLEST PERIODIC
TE/TIME = 05/19/24 6:10
THOD = CSLD Periodic Test
URS = 23
G. VOLUME = 7395
VOLUME = 61.5

PORT TYPE = FULLEST PERIODIC
TE/TIME = 04/28/24 7:22
THOD = CSLD Periodic Test
JRS = 23
G. VOLUME = 7569
VOLUME = 62.9

PORT TYPE = FULLEST PERIODIC
TE/TIME = 03/19/24 2:12
THOD = CSLD Periodic Test
JRS = 18
G. VOLUME = 7506
VOLUME = 62.4

PORT TYPE = FULLEST PERIODIC
TE/TIME = 02/26/24 4:05
THOD = CSLD Periodic Test
= 26

/03/24 4:07 PM

9379 GPM # 5637

499 US HWY 20

UTH BEND, IN 46628

4-287-0837

nsor Status Report -
1 Sensors

DATA AVAILABLE